



Villa Aesthetica

The interior of the clinic is supposed to open up for conversation about the meaning of beauty. The materials used in this project are considered classic and beautiful: marble, ash wood, linen. But they are contrasted with materials from opposite side of the spectrum, eg. old, cracked plaster. The walls are decorated with the graphics of close ups from Flemish portraits, since the standards of beauty have changed since then. That brings up the perspective on what's beauty and how it changes during the years that go by.




marble tiles



old plaster wall




ash wood



1st floor
doctor's offices,
waiting room



ground floor
doctor's offices,
reception,
waiting room



-1
office,
massage room,
floating room

3 condignations view